


Community Center Park

Existing Batting Cage Frame



New Tennis Backboard (fit within 2 Fence Posts)



Existing Play System



Warped and broken landscaping ties to be replaced as required around court.

Asphalt to be repaired – cracks sealed and broken parts repaired. Stripe for 1/2 basketball court

Existing Basketball court




Metal fencing to be re-secured to posts – both sides, and at the top.


Repair Activities

Community Center Park

Scrape surface at least 3 inches and lay wood mulch. Provide wood landscape ties as border and join with existing ties.




Place 2 round head carriage bolts in 2 top holes to straighten backboard.



Repair Activities

Community Center Park



New Equipment